





Exterior

Overall White with Sky Blue and Cherry Red accent stripes.





1994 Bombardier Learjet 31A

N480ME Serial Number 31A-085

Airframe

6666.3 Total Hours 5431 Total Landings

Engines

Honeywell TFE 731-2-3B on MSP Gold Left Engine - S/N P-99280 6671.1 Total Hours Since new 5389 Total Cycles Since New 435.1 Hours Until MPI

Right Engine - S/N P-99279 6486.4 Total Hours Since New 5416 Total Cycles Since New 435.1 Hours Until MPI

Weights

Maximum Ramp 17,900 Lbs. Maximum Take-off 17,700 Lbs. Maximum 0 Fuel Weight 13,500 Lbs. Basic Empty Weight 10,678 Lbs.

Avionics

Bendix/King KFC-3100 IFCS Dual Bendix/King VC-401B Comms Dual Bendix/King VN-411B Navs Bendix/King DM-441B DME Bendix/King DF-431B ADF Bendix/King GPS-1000 GPS Receiver Bendix/King KRA-405 Radar Altimeter Bendix/King RDS-84VP Weather Radar Universal UNS-1B Flight Management System Sandel ST3400 TAWS Bendix/King KTA-910 TCAS I Dual Garmin GTX-345R/GTX-335R ADS-B Transponders Dual Bendix/King KAU-461 AHRS Computers Dual Bendix/King KDC-481T Air Data Computers Universal Solid State Data Transfer Unit Emerging Lifesaving Technologies ELT406GPS

Universal CVR-30A Cockpit Voice Recorder

Additional Features

Honeywell MSP Gold Engine Program
Dee Howard TR-4000 Thrust Reversers
Freon Air Conditioning
Cargo Door
Honeywell N1 DEEC Upgrade
Dual Hot Liquid Containers
Belted Lavatory Seat
ADS-B Out
IDC Standby Altimeter
Dual Davtron M877 Digital Clocks
Gill Lead Acid Batteries

Other

12 Year Airframe Inspection Due 12/29 CAMP Maintenance Program



Interior

The eight-passenger interior features a four-place center club configuration in mid cabin, aft three-place bench seat, and a single side-facing belted lavatory seat located forward opposite the entry door. All seating is completed in Navy Blue leather accented with a Navy Blue sculptured carpet. Cabin furnishings include a slimline forward refreshment center with dual heated Mapco's and dual executive tables. All cabinetry is completed in Maple and complemented with brushed aluminum metal surfaces throughout the cabin.





























Specifications and/or descriptions are provided as introductory information only, and do not constitute representations or warranties of Pinnacle Aviation.

Accordingly, you should rely on your own inspection of the aircraft. Subject to prior sale.





For 35 years Pinnacle Aviation's team of experts has provided sales and aircraft solutions by listening to your needs. We then go to work and apply our knowledge of the current market and guide you in making the right choice. If you would like further information on this Learjet 31A, please contact Pinnacle Aviation at 800.333.1680.









