



1981 TURBO COMMANDER 840 N885LV SERIAL NUMBER 11680



Exterior

Overall Matterhorn White with Dark Blue and Gray accent stripes.



1981 Turbo Commander 840

N885LV Serial Number 11680

Airframe

8460 Total Hours

Engines

Garrett TPE331-10T-511K

Left Engine - S/N P-79683C

10 Hours Since Major Overhaul

Right Engine - S/N P-79682C

10 Hours Since Major Overhaul

Propellers

5-Blade MT Propellers

Left Propeller - S/N 180940

10 Hours Since Overhaul

Right Propeller - S/N 180941

10 Hours Since Overhaul

Avionics

Dual Garmin-G600 PFD/MFD

Garmin GMA-35 Audio Panel

Garmin GTN-750 GPS/NAV/COMM

Garmin GTN-650 GPS/NAV/COMM

Garmin GTX-345R/GTX-33ES Transponders

Dual Garmin GRS-77 AHRS

Garmin GWX-70 Weather Radar

Garmin GDL-69A SiriusXM Satellite Weather

Garmin Flight Stream 510

Extant Aerospace TRC899 TCAS I

S-TEC 2100 Autopilot

Additional Features

Camera Hole (*Currently in Passenger Configuration*)

Optical Quality "Photographic Glass"

Emergency Exit Window

Keith Air Conditioning

Enviro Environmental System

Oxygen System

Pulselite Control Bird-Strike Protection Light System

Whelen Rotating Beacon

Artex ELT-200 With Panel Mounted Switch

Other

Complete Logbooks

425 Gallon Fuel Capacity

3322 Lbs Useful Load

Gear Overhauled by National Flight Services in 2025

Large Aft Baggage Compartment

Hard Landing Incident in 2025, Repaired by Global Aviation Services

Minor Delamination on Left Windscreen

Right Windscreen Replaced in 2022



**Interior**

The six passenger interior features an aft five place club configuration and forward side facing seat. All seats are completed in dark Gray leather. The forward side facing seat includes a non-flushing lavatory. Cabin furnishings include a folding executive table, window curtains, pilot and co-pilot sheepskin seat covers, and a seven place intercom system. The interior can be converted to an aerial survey configuration. Interior was refurbished in 2014 by Interior Executive Aircraft Maintenance.



Specifications and/or descriptions are provided as introductory information only, and do not constitute representations or warranties of Pinnacle Aviation. Accordingly, you should rely on your own inspection of the aircraft. Subject to prior sale.











For over 35 years Pinnacle Aviation's team of experts has provided sales and aircraft solutions by listening to your needs. We then go to work and apply our knowledge of the current market and guide you in making the right choice. If you would like further information on this Turbo Commander 840, please contact Pinnacle Aviation at 800.333.1680.



14988 N 78TH WAY SUITE 106 SCOTTSDALE ARIZONA 85260 SALES@PINNACLEAVIATION.COM WWW.PINNACLEAVIATION.COM

