





Exterior

Overall White with Sky Blue and Cherry Red accent stripes.





# 1994 Bombardier Learjet 31A

N480ME Serial Number 31A-085

#### **Airframe**

6666.3 Total Hours 5431 Total Landings

### **Engines**

Honeywell TFE 731-2-3B on MSP Gold Left Engine - S/N P-99280 6671.1 Total Hours Since new 5389 Total Cycles Since New 435.1 Hours Until MPI

Right Engine - S/N P-99279 6486.4 Total Hours Since New 5416 Total Cycles Since New 435.1 Hours Until MPI

## Weights

Maximum Ramp 17,900 Lbs.

Maximum Take-off 17,700 Lbs.

Maximum 0 Fuel Weight 13,500 Lbs.

Basic Empty Weight 10,678 Lbs.

#### **Avionics**

Bendix/King KFC-3100 IFCS

Dual Bendix/King VC-401B Comms

Dual Bendix/King VN-411B Navs

Bendix/King DM-441B DME

Bendix/King DF-431B ADF

Bendix/King GPS-1000 GPS Receiver

Bendix/King KRA-405 Radar Altimeter

Bendix/King RDS-84VP Weather Radar

Universal UNS-1EW FMS with WAAS

Sandel ST3400 TAWS

Bendix/King KTA-910 TCAS I

Dual Garmin GTX-345R/GTX-335R ADS-B Transponders

Dual Bendix/King KAU-461 AHRS Computers

Universal Solid State Data Transfer Unit

Emerging Lifesaving Technologies ELT406GPS

Universal CVR-30A Cockpit Voice Recorder

### **Additional Features**

Honeywell MSP Gold Engine Program
Dee Howard TR-4000 Thrust Reversers
Freon Air Conditioning
Cargo Door
Honeywell N1 DEEC Upgrade
Dual Hot Liquid Containers
Belted Lavatory Seat
ADS-B Out
IDC Standby Altimeter
Dual Davtron M877 Digital Clocks
Gill Lead Acid Batteries

#### Other

12 Year Airframe Inspection Due 12/29 CAMP Maintenance Program



## Interior

The eight-passenger interior features a four-place center club configuration in mid cabin, aft three-place bench seat, and a single side-facing belted lavatory seat located forward opposite the entry door. All seating is completed in Navy Blue leather accented with a Navy Blue sculptured carpet. Cabin furnishings include a slimline forward refreshment center with dual heated Mapco's and dual executive tables. All cabinetry is completed in Maple and complemented with brushed aluminum metal surfaces throughout the cabin.





























Specifications and/or descriptions are provided as introductory information only, and do not constitute representations or warranties of Pinnacle Aviation.

Accordingly, you should rely on your own inspection of the aircraft. Subject to prior sale.





For 35 years Pinnacle Aviation's team of experts has provided sales and aircraft solutions by listening to your needs. We then go to work and apply our knowledge of the current market and guide you in making the right choice. If you would like further information on this Learjet 31A, please contact Pinnacle Aviation at 800.333.1680.









