





Exterior

Overall White with Green and Black accent stripes.





2004 Bombardier Learjet 40

CC-CMS Serial Number 45-2009

Airframe

5653.0 Total Hours 3101 Total Landings

Engines

Honeywell TFE731-20AR-1B on MSP Gold Left Engine - S/N P116499 5653.0 Total Hours, 3101 Total Cycles

Right Engine - S/N P116500 5653.0 Total Hours, 3101 Total Cycles

Auxiliary Power Unit

Honeywell RE-100 on MSP Gold S/N P264 1671.7 Total Hours 3742 Total Starts

Weights

_	
Maximum Ramp	20,600 Lbs.
Maximum Take-off	20,350 Lbs.
Maximum Landing	19,200 Lbs.
Maximum 0 Fuel Weight	16,000 Lbs.
Basic Empty Weight	13,724 Lbs.
Basic Empty Weight	13,789 Lbs.
(With Stretcher)	

Avionics

Honeywell Primus 1000 System Four (4) Tube DU-870 EFIS/MFD with 7" x 8" Displays Engine Instrument/Crew Alerting System (EICAS) Dual Honeywell RM-855 Radio Management Units Dual Honeywell AV-850A Audio Control Panel Dual Honeywell RCZ-833M Integrated Comms (8.33 MHZ) Dual Honeywell RNZ-851/RNZ-851B Integrated **Nav Units** Dual Honeywell IC-600 Integrated Avionics Computers Dual Universal UNS-1E FMS with GPS Dual Honeywell AZ-950 Air Data Computers Dual Honeywell DA-800 Digital Acquisition Units Dual Honeywell LCR-93 AHRS Computers Honeywell Primus WU-880 Weather Radar Honeywell RT-300 Radio Altimeter Dual Honeywell XS-850 Mode S Transponders Honeywell TCAS 2000 TCAS II with Change 7.0 Honeywell Mark V Enhanced GPWS Honeywell AFIS Honeywell KHF-950 HF with Selcal Universal DTU-100 Data Transfer Unit

L3Harris FA2100 Flight Data Recorder Honeywell SSCVR Cockpit Voice Recorder Artex C406-2 Emergency Locator Transmitter

Additional Features

Honeywell MSP Gold Engine Program (Currently \$496.64 per engine/hr)
Optional Spectrum Aeromed Stretcher Unit
Airshow Genesys Cabin Information System
10.4" LCD Monitors on Forward and Aft Bulkheads
CD Changer/DVD Player
Seat Storage Drawers
(3) 110VAC Cabin Outlets
Dual Davtron M850 Digital Clocks
Flightstar ADS-B Out
Cockpit Sunvisors
New Concorde Lead Acid Batteries
Aerosonic Standby Altimeter
Aerosonic Standby Airspeed
Extended Duration Oxygen System

Other

One Owner Since New
CAMP Maintenance Program
1200 Hour/48 Month Inspections Completed 02/24



Interior


The 6 passenger interior features a forward four-place club arrangement and two seats facing forward located aft, with seating completed in Tan leather and accented with a light Tan carpet. The headliner, cabin window and accent panels are Off-White Ultraleather complemented with Bubinga veneer woodwork throughout cabin finished in a high-gloss finish and accented with brushed nickel metal hardware. An aft baggage compartment is located opposite the aft lavatory. The forward right-hand galley features a heated liquid container, ice drawer, and various storage drawers. Passenger amenities include two 10.4" LCD monitors located in the forward and aft bulkheads that display the Airshow Genesys cabin information system, a CD/DVD player, and three 110VAC cabin outlets. An optional Spectrum Aeromed stretcher unit is included as well.




































Specifications and/or descriptions are provided as introductory information only, and do not constitute representations or warranties of Pinnacle Aviation. Accordingly, you should rely on your own inspection of the aircraft. Subject to prior sale.





For 35 years Pinnacle Aviation's team of experts has provided sales and aircraft solutions by listening to your needs. We then go to work and apply our knowledge of the current market and guide you in making the right choice. If you would like further information on this Learjet 40, please contact Pinnacle Aviation at 800.333.1680.







